

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIG. 1




FIG 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG 7




FIG. 8




FIG. 9




FIG. 10

FIG. 11B





FIG. 11A

FIG. 12





FIG. 13






FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22





FIG. 23


BEST AVAILABLE COPY



Negative can
be in either of these
four places

FIG 24

BEST AVAILABLE COPY



Negative terminal is here

Need to run shunt
wires through here
(or opposite side)

FIG 25




FIG. 26




FIG. 27









FIG. 28






FIG 29



Unless noted, all wires
are 28 gauge stranded




FIG. 31




FIG. 32




FIG. 33




FIG. 34





FIG. 35




FIG 36




FIG. 37




FIG. 38



FIG. 39




FIG. 40




FIG. 41




FIG. 42




FIG. 43




FIG. 44




FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53




FIG. 54




FIG. 55




FIG. 50





FIG. 57






FIG. 59




FIG. 60




FIG. 601

30B
d




FIG. 602




Fig. 63




FIG. 64




FIG. 65




FIG. 606




FIG. 67




FIG. 68




FIG. 69